Map Findings 2018

Map Id: 5 Direction: SE Distance: 0.520 mi. Actual: 2744.331 ft.

Elevation: 0.025 mi. / 134.039 ft.

Relative: Lower

Site Name: N/R

149 River Rd WHATELY, MA

Database(s): [LEAD - MA] (cont.)

Envirosite ID: 1003488

EPA ID: N/R

LEAD - MA (cont.)

Outcome:

Hazards Found - At the time of inspection there were lead hazard found on the property. The inspection showed areas that did not meet Massachusetts rules for lead safety. Lead paint was found in poor condition (chipping or peeling), or on areas of windows that could make dust, or in areas where young children could reach it. Under Massachusetts rules, these areas must be deleaded if there are children under 6 years old living there.

Map Id: B6 Direction: NNE Distance: 0.608 mi. Actual: 3210.166 ft.

Elevation: 0.028 mi. / 147.054 ft.

Relative: Higher

Site Name: N/R

267 RIVER RD DEERFIELD, MA

Database(s): [ERNS]

Envirosite ID: 316230178

EPA ID: N/R

ERNS

Facility Address: 267 RIVER RD, DEERFIELD, MA

County: FRANKLIN

Incident Information

Incident Date Time: 08/03/2015 12:00 PM

Type of Incident: FIXED
Incident Cause: DUMPING
Incident DTG: OCCURRED
Incident Location: N/R
Sequence Number: 1132458
Potential Flag: N

Description of Incident: CALLER STATED THAT THE OWNER OF THE COMPANY IS DUMPING

AUTOMOTIVE OILS ONTO THE GROUND. CALLER STATED THERE IS A

CONSERVATION AREA THAT IS AT THE BOTTOM OF THE HILL.

Incident Response Summary

 Date Time Received :
 11/03/2015 12:35 PM

 Date Time Completed :
 11/03/2015 12:41 PM

Call Type : Incident
Source : TELEPHONE

Responsible Company: DEERFIELD AUTO WRECKING Responsible Org Type: PRIVATE ENTERPRISE

Responsible City : GREENFIELD

Responsible State : MA
Responsible Zip : N/R

Map Findings 2018

Map Id: B6 Direction: NNE Distance: 0.608 mi. Actual: 3210.166 ft.

Elevation: 0.028 mi. / 147.054 ft.

Relative: Higher

Site Name: N/R

267 RIVER RD DEERFIELD, MA

Database(s): [ERNS] (cont.)

Envirosite ID: 316230178

EPA ID: N/R

ERNS (cont.)

Incident Details Summary

Remedial Action:

Medium:
LOCAL POND
Medium Description:
WATER
Body of Water:
LOCAL POND
Weather Conditions:
UNKNOWN
Water Temperature:
N/R

Water Supply Contaminated : U
Waterway Closed : N
Waterway Description : N/R

Additional Incident Details Summary

Actual Amount: N/R Actual Amount Units: N/R Capacity of Tank: N/R Capacity of Tank Units: N/R Continuous Release Begin Date: N/R Continuous Release End Date: N/R Continuous Release Change Date: N/R Continuous Release Permit: N/R Continuous Release Type: N/R Description of Tank: N/R Device Operational : П DOT Crossing Number: N/R DOT Regulated: U NPDES : N/R NPDES Compliance: U Pipeline Aboveground : ABOVE Pipeline Covered : Pipeline Type: N/R Tank ID: N/R Tank Regulated: U N/R Tank Regulated by:

Materials Involved Summary

Name of Material : AUTOMOTIVE OILS CAS Number : 000000-00-0

Amount of Material :

Unit of Measure : UNKNOWN AMOUNT

UN Number: N/R
CHRIS Code: OTH
Reached Water: YES
Amount in Water: 0

Unit of Measure (Reach Water): UNKNOWN AMOUNT

Additional Materials Involved Summary

Name of Material : N/R
CAS Number : N/R
CHRIS Code : N/R
Upper Bounds : N/R
Upper Bounds Unit : N/R

Map Findings 2018

Map Id: B6 Direction: NNE Distance: 0.608 mi. Actual: 3210.166 ft.

Elevation: 0.028 mi. / 147.054 ft.

Relative: Higher

Site Name: N/R

267 RIVER RD DEERFIELD, MA

Database(s): [ERNS] (cont.)

Envirosite ID: 316230178

EPA ID: N/R

ERNS (cont.)

Upper Bounds Rate: N/R

Trains Details

Train Name Number: N/R Train Type: N/R Train Speed: N/R Train Direction: N/R Number Locomotives: N/R Number Cars: N/R Number Derailed : N/R Track Speed: N/R Railroad Name: N/R Non Compliance with Hazmat: N/R

Derailed Units Summary

Train Name Number: N/R
Car Number: N/R
Car Content: N/R
Position in Train: N/R
Derailed Type: N/R

Vessels Details

Vessel Name : N/R Vessel Type: N/R Vessel Length: N/R Hull Construction: N/R Fuel Capacity: N/R Fuel on Board: N/R Cargo Capacity: N/R Cargo on Board: N/R Is Vessel Aground: N/R N/R Flag: Breadth: N/R Draught: N/R Fuel Capacity Units: N/R Fuel on Board Units: N/R Cargo Capacity Units: N/R Cargo on Board Units: N/R

Mobile Details

Vehicle Own Fuel Capacity: N/R Cargo Capacity: N/R Amount of Cargo on Board: N/R N/R Hazmat Carrier: Carrier Licensed: N/R Noncompliance with Hazmat: N/R Mobile Type: N/R Cargo Capacity Units: N/R Amount of Cargo on Board Units: N/R